

Work Order:	24247
-------------	-------

Part Number:	D3393-041
--------------	-----------

Page 1 of 1

Slp	Location	Procedure	By	Date	Qty
1	DC	Issue Traveller			
1	ACS	Inspect D3393-041 for damage key: C420A B23520 Qty 1		05-05-13	3
		CS87A B22710 Qty 1			
		C148A B22710 Qty 1			
2	GA	re-work D3393-041 key C148A B22710	SR	05/09/15	
		by removing lock and replace lock keyed B#B22293 key #085A unlike, Assemble as per Dwg D3393			
3	QCS	Inspect lock rework		05-05-15	
4	WS	Jack lightly D3353-3 to D3353-5	PD	05-09-15	
5	QC95	Inspect + Jack weld ensure lock works freely.		05-09-15	3
6	PK	re-stock locks D3353-041	CD	05/09/15	3
7	QC21			05/09/15	3
8	DC	Close w/o		05-05-13	3

DART AEROSPACE LTD		Work Order:	12710
Description: Dual Disabling Kit (Medium Bell)		Part Number:	D412-738-011
		Keyed:	<input type="checkbox"/> Alike <input checked="" type="checkbox"/> Unlike
Dwg: D3368 Rev. A; D3369 Rev. A1 page 4; D3371 Rev. A page 4; D3393 Rev. A page 1		Qty:	88 33 Page 3 of 3

D3368-041 Key Numbers	D3393-041 Key Numbers
	C579A ✓
	C363A ✓
	C181A ✓
	C057A ✓
	C590A ✓
	C061A ✓
	C076A ✓
	C162A ✓
	C576A ✓
	C574A ✓
	C587A ✓
	C316A ✓
	C079A ✓
	C094A ✓
	C573A ✓
	C091A ✓
	C086A ✓
	C418A ✓
	C572A ✓
	C525A ✓
	C139A ✓
	C440A ✓
	C104A ✓
	C177A ✓
	C415A ✓
	C014A ✓
	C103A ✓
	C144A ✓
	C554A ✓
	C403A ✓
	C087A ✓
	C201A ✓
	C581A ✓
	C372A ✓
	C148A ✓

Change (C) for 05-05-13

Rev	Date	Change	Revised By	Approved
A	05.02.01	New Issue	KJ/JLM	
B	05.02.18	Revised procedures	KJ/JLM	
C	05.02.24	Revised Steps 6, 8 & 14	KJ/JLM	

PLEASE